TEST REPORT

Applicant : HAKYOR INTEL LTD

Address : A.Haydarov st 25a,Andijan city,Rep. Of Uzbelistan

The following sample information is supplied by the customers:

Sample Name : Deflector ASM-FRT S/D Wat& Deflector ASM-FRT S/D Wat

Model : GSVEM/JBSC/JBUC

Part No. : 52021971/52021972/94768342/94768343/26353842/26353843/26397838/26397839/26397840/26397841/52183543/52183544/52183545/52183546/52183547/52183548

Material : Polyethylene

OEM : UzAutoMotors

Manufacturer : /

Supplier : /

Date of Receipt : Mar. 23, 2026

Date of Test : Mar. 30, 2026 to Mar. 31, 2026

Test Summary :

No.	Test Item	Test basis	Conclusion
1	Water leak test	GMW15523sec.3.6 and customer requirements	Fail
2	Adhesion	GMW15523sec.3.7 and customer requirements	Fail

Note：Pass：Meet requirement；Fail：Not meet requirement；N/A：Do not evaluate or provide test results only

******FOR FURTHER DETAILS, PLEASE REFER TO THE FOLLOWING PAGE(S) ******

Signed for and on behalf of

Jiangsu 3E-TEST Technology Co., Ltd

Prepared by:	Reviewed by:	Approved by:
Alisa, Wang	Kris, Tao	Irwin, Dong
Project Engineer	Project Leader	Technical Director

1 Test Item：Water leak test

1.1 Environmental Condition：

Temperature：23.1℃；Relative Humidity：48%RH

1.2 Test Basis：

GMW15523sec.3.6 and customer requirements

1.3 Test Condition：

a) A bead of material 6 mm in diameter or a film of pressure sensitive adhesive 25 mm wide and 275 mm long shall be applied (using production equivalent equipment and process) in a "U" configuration to a 100 mm x 100 mm painted panel (representing the door inner) and rolled with a 2000 g roller once in one direction to insure contact. Fill the "U" with colored water and place over white paper towels. Examine after 24 h at room temperature for any signs of water leakage.

b) Repeat assembly of test fixture as in a) Submit this test fixture to one 1 cycle of GMW14124,Cycle W. After cycle test, allow test fixture to set for 1 h per GMW3221, Code A. Fill the "U" with colored water and place over white paper towels. Examine after 24 h at room temperature for any signs of water leakage.

1.4 Test Result：

No.	Test result	Technical requirements	Test conclusion
1	Leakage after 67 minutes	It does not leak for more than 24 hours	Fail
2	Leakage after 72 minutes		

1.5 Test Photo:




Fig.1-1 Sample photo




Fig.1-2 Water leak test photo



Fig.1-3 Water leak test photo

2 Test Item：Adhesion

2.1 Test Equipment：

Equipment name	No.	Calibration validity period
Electronic universal testing machine	E/A-QT-145	2026.07.15

2.2 Environmental Condition：

Temperature：23.1 ℃； Relative Humidity：51 %RH

2.3 Test Basis：

GMW15523sec.3.7 and customer requirements

2.4 Test Result：

No.	Adhesion N /m	
	（23℃ 5min）	(23℃ 15min)
1	73.2	78.4
2	73.6	79.3
3	73.3	78.7
Technical requirements	＞150	＞200
Test conclusion	Fail	Fail

2.5 Test Photo:




Fig.2-1 Sample photo




Fig.2-2 Adhesion test photo




Fig.2-3 Test curve(23℃ 5min)




Fig.2-4 Test curve(23℃ 15min)




Fig.2-5 Sample photo after the test(23℃ 5min)




Fig.2-6 Sample photo after the test(23℃ 15min)

*** End of Report ***

TEST REPORT

报告声明
Report Statement

1. 本报告仅限三亿客户使用，依照三亿和客户之间的协议产生。
   The test report is for the exclusive of 3E's Client and is provided pursuant to the agreement between 3E and its client.

2. 本报告无授权签字人签字及加盖“检验检测专用章”无效。
   The test report is effective only with both signatures and specialized stamp.

3. 本报告只有客户有权利复制、发布完整的报告。
   The test report is only the Client is authorized to permit copying or distribution of this report and then only in its entirety.

4. 本报告样品信息为客户提供，不对其真实性负责。
   The source information of the sample in this report is supplied by the customer without any responsibility for the authenticity of its source information.

5. 本报告以实测值进行符合性判定，未考虑不确定度所带来的风险，特别约定、标准或规范中有明确规定的除外。
   The judgment method of determining the conformity in this test report is according to the measured value without considering the risk caused by uncertainty, unless otherwise clearly stipulated in special agreement, standard or specification.

6. 本报告仅对被测试样品的测试结果负责，未加盖资质认定标志的检测报告不对社会具有公正证明作用。
   The test report is only responsible for the test results of the tested sample. If the report is not marked with CMA, it means that the test data and results does not have the function of proving to the society.

7. 如对本报告有异议，可在收到报告之日起 30 天内向本实验室申诉，逾期不予受理。
   Telling the 3E in 30 days since you receive the report when you don't agree, otherwise it is not accepted.

8. 本报告如有特别用途时应提前告知本实验室，如法律、诉讼、司法鉴定等。若未提前告知，本实验室概不承担任何法律责任。
   If the test report is used for special purpose, the laboratory should be informed in advance, such as law, litigation, judicial expertise, etc. Without prior to inform the laboratory, 3E is not responsible any legal consequences.

9. 本报告可通过登录网站 www.3e-test.com 或拨打电话 0512-57907288 进行防伪验证。
   The test report can be verified for anti-counterfeiting by logging into the website www.3e-test.com or calling 0512-57907288.

10. 本报告的最终解释权归江苏三亿检测技术有限公司所有。
    The final interpretation of this report is owned by Jiangsu 3E testing technology co., LTD.